

## Compliance Inspection Checklist PG 5/2 - Crematoria

Pollution Prevention and Control Act 1999 Environmental Permitting (England and Wales) Regulations 2016

Company Name:	Barrow Borough Council						
Address of Premises:	Thorncliffe Crematorium						
Date of Inspection:	17 <sup>th</sup> Mar	rch 2	2022	Start time:	09.30am		
Site Contact:	Chris Po	llard		Finish time:			
Inspector:	Alison Co	owa	rd	Duration:			
Reason for Inspection:	Annual Inspection 2021-22						
Information required by the regulator	Yes N	No	Comments				
Notify 7 days before annual monitoring	<b>√</b>						
Annual Monitoring results received within 8 weeks	<b>√</b>		Monitoring carried out 6 <sup>th</sup> Jan,	results forward	led 3 <sup>rd</sup> Feb.		
CEM results received every 6 months	<b>✓</b>		Usually sent quarterly.				
Emissions	Yes N	lo	Comments				
Compliant with all relevant emission limits	<b>✓</b>						
Visible emissions at boundary		<b>√</b>					
Offensive odour beyond boundary		<b>√</b>					
Monitoring, Investigations & Recording	Yes N	No	Comments				
Available and up to date	<b>√</b>		_				
Daily assessments recorded	<b>√</b>		Recorded online.				

Summary of CEM results	<b>✓</b>		
Annual emissions testing	<b>✓</b>		
Adverse results recorded		<b>√</b>	
Maintenance work recorded	<b>✓</b>		Last service undertaken on 13-16 <sup>th</sup> December 2021.
Abnormal emissions / events	<b>✓</b>		Intermittent issue with compressor / electrics causing trip outs and log recording bypass instead of abatement.
Control of Operations	Yes	No	Comments
Controls on coffin construction and content	<b>✓</b>		
Volume of secondary combustion zone known	<b>✓</b>		
Maintenance programme	<b>✓</b>		Contract for biannual servicing, with additional work when needed.
Staff training	<b>✓</b>		Additional staff were trained during covid to provide extra capacity should it be needed.
Compliant	Yes	No	Comments
If no, what corrective	✓		
action is required			
Corrective Action /			
Recommendations			
Other observations			
	ue not v	et res	olved, despite different contractors trying to remedy. To be looked at
again by PJ Combustion in	-		,