

Compliance Inspection Checklist PG 5/2 - Crematoria

Pollution Prevention and Control Act 1999 Environmental Permitting (England and Wales) Regulations 2010

Company Name:	Barrow Borough Council					
Address of Premises:	Thorncliffe Crematorium					
Date of Inspection:	9 th December 2016			Start time:	10.00am	
Site Contact:	Chris Pollard / Louise Bland			Finish time:	11.00am	
Inspector:	Geoff Dowker/ Simon O'hara			Duration:	1 hour	
Reason for Inspection:	Annual Inspection 2016-17					
Information required by						
the regulator	Yes	No	Comments			
Notify 7 days before	х		Notified on 10 th October 2016, Subsequent change notified on 30 th November			
annual monitoring			2016. (Reason- Minimal Cremation	•		
Annual Monitoring	x		Monitoring carried out on 7 th & 8 th December 2015, results received 23 rd December 2015. Next Monitoring round is 11 th &12 th January 2017.			
results received within 8 weeks			23 December 2015. Next Monitor	ing round is 11 ^{°°8}	د12 [™] January 2017.	
CEM results received	x		Results received monthly, some	e reporting issue	es remain. *See below*	
every 6 months						
Emissions	Yes	No	Comments			
Compliant with all	х		Annual Monitoring demonstrates of	-	-	
relevant emission limits			reported monthly are inaccurate- structure.	inherent to softwa	are and reporting	
Visible emissions at		x	None reported			
boundary						
Offensive odour beyond		х	None reported			
boundary						
Monitoring, Investigations & Recording	Yes	No	Comments			
Available and up to date	x		Yes-See box below			
Daily assessments	x		Kept on Site			
recorded						

Summary of CEM results	x		New template format used but not ideal (however, template is used by numerous Authorities)			
Annual emissions testing	x		Report produced by Catalyst Environmental- compliant and up to date. However report does not reflect CEM manual monitoring levels for same cremation.			
Adverse results recorded		x	CEM monitors potentially not working and computer program/ software needs alteration to average readouts and figure is skewed. (i.e. Averages of 0 for CO.)			
Maintenance work recorded	x	x New Refurbishment of crematorium including offices, new chapel layout and employee provisions. (*Cremator room unaltered)				
Abnormal emissions / events		X	Emissions exceeded particulate limits by 3% of cremations. (Noted 3 rd October 2016) Investigation had determined that an engineer had been on site and system was taken offline momentarily- therefore the results were skewed and not representative.			
Control of Operations	Yes	No	Comments			
Controls on coffin construction and content	x					
Volume of secondary combustion zone known	x		SEE Compliance Inspection Checklist dated 26 th January 2012			
Maintenance programme	x		As and when needed.			
Staff training	x		4 Fully qualified staff now present on site.			
Compliant	Yes	No	Comments			
If no, what corrective	х					
action is required						
Corrective Action / Recommendations	None					
Other charactions						
Other observations						
 CAMEO Certification for 2016 Received on 11th April 2016. Pandemic Planning Procedure obtained Possible cremator replacement in 2018/19 						