

**Burlington Aggregates Ltd**

**PPC Inspection Sheet – Mobile Crushing and Screening Plant PPC/B/02**

INC.

PPC/18/29 +  
PPC/18/30

1. Equipment covered by permit changed? NO . SEE NOTES;
2. Visual assessment of emissions made at least once a day? Time, location and result recorded? ✓
3. Problems, i.e. airborne dust recorded and corrective action taken? ✓ YES .
4. Stockpiles – loading to and from, construction and management – minimising wind-borne dust. Conditioned with water if necessary? Water on site? BOWSER ✓
5. Material stored in open – screened to remove 3mm and under
  - sand ✓
  - scalpings ✓
  - Crusher run material conditioned with water before deposition ✓
6. Water suppression on crusher aperture? YES ✓
7. Conveyors enclosed to prevent wind whipping if material less than 3mm. YES . FRONT NOT SIDE ✓
8. Conveyors kept clean, catch plate fitted? ✓
9. Water at conveyor discharge points? (not necessary if under 3mm removed). ✓
10. Last metre of final discharge conveyor and first 0.5m – full hood? ✓ YES .
11. Vehicles sheeted? NONE .
12. Training records? YES . ON SITE ✓
13. Maintenance? YES . UNDER WARRANTY .
14. When crusher hired out
  - operator goes with it? YES ✓
  - copy of permit with it? YES AS NOTIFIED .
  - fax to Barrow Council and Local Authority moving into if different.? YES SEE BELOW!

Extra Notes: EMAIL RECEIVED 13-01-17

GOLDMIRE QUARRY – EXTEC S3, E7, C12 & IMPACT CRUSHER  
– SANDVIK QI441.

ROOSE SAND/CORREL – EXTEC S3

KIRKBY – SANDVIK QE341

ELTZELWATER – SANDVIK QE440 / QE340.